
# VöGELE KETTENFERTIGER SUPER 1800-2

| GENERAL | | BILDER |
|---|---|---|
| ID | 18731 |  |
| Year | 2009 | |
| Working hours | 11532 | |
| Weight [to] | 22,3 | |
| | | |
| **ENGINE SPECIFICATION** | | |
| Manufacturer | Perkins | |
| Engine [type] | 1006-6 | |
| Engine rating [kW] | 129,6 | |
| **EQUIPMENT** | | |
| Screed [type] | AB 500-2 TV | |
| Tamper / vibrators | ✓ | |
| Electric heating | ✓ | |
| Pave width [m] | 2,5 - 5m | |
| Extensions | 2x 0,75m | |
| Level control | ✓ | |
| Height sensor - sonar [pieces] | 2 | |
| Auger sensors mech. | ✓ | |
| Auger sensor - sonic | ✓ | |
| Slope control sensor | ✓ | |
| central lubrication | ✓ | |

| CONDITION | | | |
|---|---|---|---|
| **ENGINE** | **STATUS** | **REMARKS** | **PICTURES** |
| Engine oil | ✓ | | |
| Leaks | ✓ | | |
| Blow by | ✓ | | |
| Engine starting | ✓ | | |
| Smoke | ✓ | | |
| Exhaust system | ✓ | | |
| Cooling | ✓ | | |
| General condition | ✓ | | |
| **HYDRAULICS** | **STATUS** | **REMARKS** | **PICTURES** |
| Hoses | ✓ | | |
| Pump | ✓ | | |
| Motors | ✓ | | |
| Cylinders | ✓ | | |
| Leaks | ✓ | | |
| General condition | ✓ | | |
| **OPERATOR´S STAND** | **STATUS** | **REMARKS** | **PICTURES** |
| Seat | ✓ | | |
| sglass pane | ✓ | | |
| Display / buttons | ✓ | | |
| General condition | ✓ | | |
| **ELECTRIC** | **STATUS** | **REMARKS** | **PICTURES** |
| lights | ✓ | | |
| Starter | ✓ | | |
| Electronic | ✓ | | |
| Battery | ✓ | | |
| General condition | ✓ | | |

| UNDERCARRIAGE | STATUS | REMARKS | PICTURES |
|---|---|---|---|
| Sprockets | 80% | | |
| Track roller | 70% | | |
| Link assy | 60% | | |
| Pads | 50% | | |
| **WEAR** | **STATUS** | **REMARKS** | **PICTURES** |
| Screed | 70% | | |
| Conveyor | 80% | | |
| Auger | 80% | | |
| **OTHERS** | **STATUS** | **REMARKS** | **PICTURES** |
| Gearbox | ✓ | | |
| Brake | ✓ | | |
| Drive | ✓ | | |
| Frame | ✓ | Aufnahme von Bunkerzylinder VL gerissen | |
| Axles | ✓ | | |
| Other | ✓ | | |