
# WIRTGEN STRAßENFRäSEN W 120 FI

| GENERAL | | BILDER |
|---|---|---|
| ID | 18576 |  |
| Year | 2014 | |
| Working hours | 6141 | |
| Weight [to] | 21,05 | |
| | | |
| **ENGINE SPECIFICATION** | | |
| Manufacturer | Cummins | |
| Engine [type] | QSL 9 | |
| Engine rating [kW] | 224 | |
| Emission standard | Tier4 | |
| EPA | ✓ | |
| exhaust gas after-treatment | ✓ | |
| **EQUIPMENT** | | |
| Milling drum [mm] | 1200 | |
| Cutting depth [mm] | 320 | |
| Folding conveyor belt | ✓ | |
| Vacuum unit | ✓ | |
| VCS - Vacuum Cutting System | ✓ | |
| LEVEL PRO | ✓ | |
| Slope control sensor | ✓ | |
| Hight sensor - cable | 2 | |
| Hight sensors (cylinder) | ✓ | |
| High pressure water cleaner | ✓ | |

| CONDITION | | | |
|---|---|---|---|
| **ENGINE** | **STATUS** | **REMARKS** | **PICTURES** |
| Engine oil | ✓ | | |
| Leaks | ✓ | | |
| Blow by | ✓ | | |
| Engine starting | ✓ | | |
| Smoke | ✓ | | |
| Exhaust system | ✓ | | |
| Cooling | ✓ | | |
| General condition | ✓ | | |
| **HYDRAULICS** | **STATUS** | **REMARKS** | **PICTURES** |
| Hoses | ✓ | | |
| Pump | ✓ | | |
| Motors | ✓ | | |
| Cylinders | ✓ | | |
| Leaks | ✓ | | |
| General condition | ✓ | | |
| **OPERATOR´S STAND** | **STATUS** | **REMARKS** | **PICTURES** |
| Seat | ✓ | | |
| Display / buttons | ✓ | | |
| General condition | ✓ | | |
| **ELECTRIC** | **STATUS** | **REMARKS** | **PICTURES** |
| lights | ✓ | | |
| Starter | ✓ | | |
| Electronic | ✓ | | |
| Battery | ✓ | | |
| General condition | ✓ | | |

| UNDERCARRIAGE | STATUS | REMARKS | PICTURES |
|---|---|---|---|
| Sprockets | 80% | | |
| Track roller | 70% | | |
| Link assy | 80% | | |
| Pads | 50% | VL: 50%; VR: 40%; HL: 80%; HR: 30% | |

| WEAR | STATUS | REMARKS | PICTURES |
|---|---|---|---|
| Primary conveyor | 30% | | |
| Discharge conveyor | 40% | | |
| Milling drum housing | 70% | | |
| Milling drum | 60% | | |
| Upper toolholder | 50% | | |
| Scraper / side plates | 20% | | |

| OTHERS | STATUS | REMARKS | PICTURES |
|---|---|---|---|
| Gearbox | ✓ | | |
| Brake | ✓ | | |
| Drive | ✓ | | |
| Frame | ✓ | Fräswalzenschutz verbogen, Bandversteifung von Abwurfband schweißnähte gerissen oder schlecht verschweißt | |
| Axles | ✓ | | |
| Other | ✓ | | |