

BOMAG WALZENZUG BW 213 D-4

GENERAL		BILDER
ID	17191	     
Year	2014	
Working hours	6592	
Weight [to]	12,5	
ENGINE SPECIFICATION		
Manufacturer	Deutz	
Engine [type]	TCD 2013 L04 2V	
Engine rating [kW]	99	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
sglass pane	✓		
Display / buttons	✓		
Heating	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓	Arbeitsscheinwerfer ohne Funktion	
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Tires bl	70%		
Tires br	70%		
WEAR	STATUS	REMARKS	PICTURES
Scraper	0%	Abstreifer Vorne und Hinten fehlen	
drum rubbers	70%	2 Bandagengummis Links leicht eingerissen	
Drum	80%	31mm	

OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		