

BOMAG TANDEMWALZE BW 100 AD-4

GENERAL		BILDER
ID	17221	     
Year	2013	
Working hours	788	
Weight [to]	2,4	
ENGINE SPECIFICATION		
Manufacturer	Kubota	
Engine [type]	D1703MDI	
Engine rating [kW]	24,3	
EPA	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓	Kraftstoffrücklaufleitung leicht schwitzig	
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
WEAR	STATUS	REMARKS	PICTURES
Scraper	40%		
drum rubbers	90%		
Drum	90%	Hinten: 12mm, Vorne: 13mm	
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		