

DYNAPAC TANDEMWALZE CC 424

GENERAL		BILDER
ID	17405	     
Year	2008	
Working hours	2894	
Weight [to]	11,1	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSB 4.5 T3	
Engine rating [kW]	82	
EPA	✓	
EQUIPMENT		
Air-conditioning	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓	Schlauch VL aufgescheuert	
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
sglass pane	✓		
Display / buttons	✓		
AC	✓		
Heating	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
WEAR	STATUS	REMARKS	PICTURES
Scraper	50%	Abstreifer an der Hinteren Bandage verschlissen	
drum rubbers	60%		
Drum	80%	Vorne & Hinten: 17mm	

OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		