# WIRTGEN STRAßENFRäSEN W 50 DCI

| GENERAL | | BILDER |
|---|---|---|
| ID | 17415 |  |
| Year | 2015 | |
| Working hours | 2013 | |
| Weight [to] | 8,9 | |
| | | |
| **ENGINE SPECIFICATION** | | |
| Manufacturer | Deutz | |
| Engine [type] | TCD 4.1 L4 | |
| Engine rating [kW] | 95 | |
| EPA | ✓ | |
| exhaust gas after-treatment | ✓ | |
| **EQUIPMENT** | | |
| Milling drum [mm] | 500 | |
| Cutting depth [mm] | 210 | |
| Conveyor belt | ✓ | |
| LEVEL PRO | ✓ | |
| Hight sensor - cable | ✓ | |

| CONDITION | | | |
|---|---|---|---|
| **ENGINE** | **STATUS** | **REMARKS** | **PICTURES** |
| Engine oil | ✓ | | |
| Leaks | ✓ | | |
| Blow by | ✓ | | |
| Engine starting | ✓ | | |
| Smoke | ✓ | | |
| Exhaust system | ✓ | | |
| Cooling | ✓ | | |
| General condition | ✓ | | |
| **HYDRAULICS** | **STATUS** | **REMARKS** | **PICTURES** |
| Hoses | ✓ | | |
| Pump | ✓ | | |
| Motors | ✓ | | |
| Cylinders | ✓ | | |
| Leaks | ✓ | | |
| General condition | ✓ | | |
| **OPERATOR´S STAND** | **STATUS** | **REMARKS** | **PICTURES** |
| Seat | ✓ | Sitzpolster leicht verschlissen |  |
| Display / buttons | ✓ | | |
| General condition | ✓ | | |
| **ELECTRIC** | **STATUS** | **REMARKS** | **PICTURES** |
| lights | ✓ | | |
| Starter | ✓ | | |
| Electronic | ✓ | | |
| Battery | ✓ | | |
| General condition | ✓ | | |

| UNDERCARRIAGE | STATUS | REMARKS | PICTURES |
|---|---|---|---|
| Tires fl | 80% | | |
| Tires fr | 80% | | |
| Tires bl | 60% | | |
| Tires br | 60% | | |
| **WEAR** | **STATUS** | **REMARKS** | **PICTURES** |
| Primary conveyor | 40% | | |
| Discharge conveyor | 60% | | |
| Milling drum housing | 80% | | |
| Milling drum | 70% | | |
| Upper toolholder | 80% | | |
| Scraper / side plates | 60% | | |
| **OTHERS** | **STATUS** | **REMARKS** | **PICTURES** |
| Gearbox | ✓ | | |
| Brake | ✓ | | |
| Drive | ✓ | | |
| Frame | ✓ | | |
| Axles | ✓ | | |
| Other | ✓ | | |