

HAMM TANDEMWALZE HD 8 VV

GENERAL		BILDER
ID	16986	     
Year	2012	
Working hours	464	
Weight [to]	1,58	
Manual	✓	
Spare part book	✓	
CE conformity	✓	
ENGINE SPECIFICATION		
Manufacturer	Kubota	
Engine [type]	D1005	
Engine rating [kW]	14,8	
Emission standard	2011 Tier4	
EPA	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓	Fahrhebel schwergängig	
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	▲	Batterie schlecht. Pole korrodiert, sollte erneuert werden	
General condition	✓		
WEAR	STATUS	REMARKS	PICTURES
Scraper	80%		
drum rubbers	70%		
OTHERS	STATUS	REMARKS	PICTURES
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		