


HAMM TANDEMWALZE HD 8 VV

GENERAL		BILDER
ID	16987	
Year	2012	
Working hours	521	
Weight [to]	1,58	
Manual	✓	
Spare part book	✓	
CE conformity	✓	
ENGINE SPECIFICATION		
Manufacturer	Kubota	
Engine [type]	D1005-ET05	
Engine rating [kW]	14,8	
Emission standard	Tier4/EPA2011	
EPA	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	⚠	Schelle zwischen Krümmer und Flexrohr undicht	
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	⊖	Abblendlicht VL ohne Funktion	
Starter	✓		
Electronic	✓		
Battery	⊖	Batteriepole korrodiert, Batteriespannung: 8V	
General condition	⚠		
WEAR	STATUS	REMARKS	PICTURES
Scraper	50%		
drum rubbers	70%		
Drum	60%	11	
OTHERS	STATUS	REMARKS	PICTURES
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		