


## BOMAG TANDEMWALZE BW 120 AD-4

GENERAL		BILDER
ID	17105	
Year	2009	
Working hours	2800	
Weight [to]	2,6	
ENGINE SPECIFICATION		
Manufacturer	Kubota	
Engine [type]	D 1703 M-EU32	
Engine rating [kW]	26,1	
EPA	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	⚠	2x Saugschlauch zu Zahnradpumpe feucht	
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	⚠	Polster beschädigt, Anschnallgurt defekt	
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	⊖	Lampe hinten Links fehlt komplett	
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
WEAR	STATUS	REMARKS	PICTURES
Scraper	50%		
drum rubbers	40%		
Drum	70%		
OTHERS	STATUS	REMARKS	PICTURES
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		