
WIRTGEN STRAßENFRäSEN W 100 FK

GENERAL		BILDER
ID	17349	
Year	2009	
Working hours	6808	
Weight [to]	18,8	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSC8.3	
Engine rating [kW]	209	
EPA	✓	
EQUIPMENT		
Milling drum [mm]	1000	
Cutting depth [mm]	320	
Folding conveyor belt	✓	
LEVEL PRO	✓	
Hight sensor - cable	✓	
High pressure water cleaner	✓	

CONDITION			
ENGINE	**STATUS**	**REMARKS**	**PICTURES**
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓	Leichte abgastrübung	
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	**STATUS**	**REMARKS**	**PICTURES**
Hoses	✓	Rücklaufschlauch von Handpumpe abgescheuert	  
Pump	✓		
Motors	✓		
Cylinders	✓	Seitenschildzylinder hinten Links leicht schwitzig, Bandhubzylinder schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR´S STAND	**STATUS**	**REMARKS**	**PICTURES**
Seat	✓	Sitzpolster verschlissen	
Display / buttons	✓		
General condition	✓		
ELECTRIC	**STATUS**	**REMARKS**	**PICTURES**
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	70%		
Track roller	80%		
Link assy	70%		
Pads	80%		
WEAR	**STATUS**	**REMARKS**	**PICTURES**
Primary conveyor	70%		
Discharge conveyor	60%		
Milling drum housing	30%		
Milling drum	70%		
Upper toolholder	70%		
Scraper / side plates	70%		
OTHERS	**STATUS**	**REMARKS**	**PICTURES**
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		