
WIRTGEN STRAßENFRäSEN W 100 FK

GENERAL		BILDER
ID	17354	
Year	2007	
Working hours	5315	
Weight [to]	19,8	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
EQUIPMENT		
Milling drum [mm]	1000	
Conveyor belt	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensor - cable	✓	

CONDITION


ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓	Motorölkühler leicht schwitzig	
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Seitenschildzylinder vorne links leicht schwitzig	
Leaks	✓		
General condition	✓		

OPERATOR´S STAND	STATUS	REMARKS	PICTURES
Seat	✓	Sitzpolster leicht abgescheuert	
Display / buttons	✓		
General condition	✓		

ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	60%		
Track roller	70%		
Link assy	80%		
Pads	40%		

WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	20%		 
Discharge conveyor	10%	Gummilaufrollen stark abgenutzt	
Milling drum housing	20%		
Milling drum	60%		
Upper toolholder	30%		
Scraper / side plates	20%		

OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		