

WIRTGEN STRAßENFRÄSEN W 200I

??????? ???? ?		BILDER
??? ?????	18292	     
??? ?????	2014	
????? ???????	7500	
????? [??]	28,4	
?????? ???????		
??????	Cummins	
??? ??????	QSX15	
??? ?????? ??????? ??	433	
??? ???????????	Tier4	
???? ?????? (???????)	✓	
???? ?????? ?????	✓	
??????????		
??? ?????? [??]	2000	
??? ?????? [??]	330	
???? ?????? ?????? ?????	✓	
??? ????? ???	✓	
?????? ??????	✓	
LEVEL PRO ????? ?????? ??????????	✓	
????? ????????	✓	
????? ?????? ?????? (?????????)	✓	
????????? ??????? ???????	✓	
?????????	✓	

??????			
??????	??????	???????	???
?? ?????	✓		
??????	✓		
??? ?????	✓		
??? ??????	✓		
?????	✓		
???????	✓		
???????	✓		
????? ??????	✓		
????????	??????	???????	???
??????	✓		
?????	✓		
?????????	✓		
????????	✓		
????????	✓		
?????? ??????	✓		
??????/?????	??????	???????	???
???????	✓	Sitzpolster Rechts und Links leicht verschlissen	
??????/ ??????	✓	Scheibe Hinten milchig	
??????	✓		
?????? ??????	✓		
????????	??????	???????	???
????????	✓		
??? ??????	✓		
?????????	✓		
?????????	✓		
?????? ??????	✓		

???????	??????	???????	???
?????	80%		
????? ?????	80%		
????? ???????	80%		
?????? ???????	70%		
???????	??????	???????	???
??? ??????? (??????)	70%		
??? ???????	50%		
????? ?????	80%		
????? ????? (???)	70%		
???????	80%		
????? / ?????	10%		
????	??????	???????	???
??????/???	✓		
?????/?????	✓		
????? ???????	✓		
?????	✓		
?????	✓		
????	✓		