


# WIRTGEN STRABENFRÄSEN W 120 FI



GENERAL		BILDER
ID	17494	
Year	2012	
Working hours	5676	
Weight [to]	21,5	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSL 9	
Engine rating [kW]	224	
Emission standard	Tier 4	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
Milling drum [mm]	1200	
Cutting depth [mm]	320	
Folding conveyor belt	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensor - cable	✓	
High pressure water cleaner	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		  
Pump	✓		
Motors	✓		
Cylinders	⚠	Abstreiferzylinder schwitzig, Seitenschildzylinder HL Kolbenstange verbogen, Aufnahmebandzylinder Kolbenstange verbogen	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	⚠	Wassertankfüllstandssensor	
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	60%		
Track roller	80%		
Link assy	70%		
Pads	60%		
WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	10%		
Discharge conveyor	20%		
Milling drum housing	90%		
Milling drum	70%		
Upper toolholder	50%	Ein Oberhalter fehlt	
Scraper / side plates	50%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	⚠	HL und Rechts fehlt ein Stück vom Dach	