

HAMM KOMBIWALZE HD 10I VT

GENERAL		BILDER
ID	18737	     
Year	2018	
Working hours	4190	
Weight [to]	2,5	
ENGINE SPECIFICATION		
Manufacturer	Kubota	
Engine [type]	D1503-M-EU33	
Engine rating [kW]	24	
Emission standard	Tier3 A	
last service [h]	4190h/30.01.26	
EPA	✓	
EQUIPMENT		
Edge cutting [pieces]	1	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Tires bl	70%		
Tires br	40%		
WEAR	STATUS	REMARKS	PICTURES
Scraper	60%		
drum rubbers	50%	Bandagengummis links verschlissen	
Drum	60%	12mm	

OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		