VOLVO KETTENFERTIGER 8820

GENERAL		BILDER
ID	17981	
Year	2005	
Working hours	15812	
Weight [to]	20,8	
Manual	✓	
Spare part book	✓	
ENGINE SPECIFICATION		
Manufacturer	Deutz	
Engine [type]	BF6M1013EC	
Engine rating [kW]	179	
Emission standard	Tier3	
EQUIPMENT		
Screed [type]	VB 78	
Tamper / vibrators	✓	
Electric heating	✓	
Pave width [m]	2,50 - 5,0	
Level control	✓	
Height sensor - sonar [pieces]	2	
Auger sensor - sonic	✓	
Slope control sensor	✓	

CONDITION			
ENGINE	**STATUS**	**REMARKS**	**PICTURES**
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	**STATUS**	**REMARKS**	**PICTURES**
Hoses	✓	Zwei Schläuche von Steuerblock HL an Verpressung schwitzig, Oberer Schlauch von Nivellierzylinder Rechts und Links an der Verpressung schwitzig	
Pump	✓		
Motors	✓		
Cylinders	✓	Bunkerzylinder Rechts leicht schwitzig	
Leaks	✓	Abdeckplatte von Hydraulikpumpe Rechts leicht schwitzig	
General condition	✓		
OPERATOR´S STAND	**STATUS**	**REMARKS**	**PICTURES**
Seat	✓	Sitzpolster Rechts verschlissen	
Display / buttons	✓		
General condition	✓		
ELECTRIC	**STATUS**	**REMARKS**	**PICTURES**
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	50%		
Track roller	70%		
Link assy	70%		
Pads	80%		
WEAR	**STATUS**	**REMARKS**	**PICTURES**
Screed	60%	Grundbohle: 90%	
Conveyor	70%		
Auger	50%		
OTHERS	**STATUS**	**REMARKS**	**PICTURES**
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		