

WIRTGEN STRAßENFRÄSEN W 100 F

GENERAL		BILDER
ID	18500	     
Year	2009	
Working hours	8588	
Weight [to]	18,8	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSC	
Engine rating [kW]	209	
Emission standard	Tier3	
EPA	✓	
EQUIPMENT		
Milling drum [mm]	1000	
Cutting depth [mm]	320	
Milling drum turning device	✓	
Folding conveyor belt	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Height sensor - cable	1	
High pressure water cleaner	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓	Motorölkühler schwitzt	
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Seitenschildzylinder rechts leicht schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓	Sitzpolster leicht verschlissen	
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	80%		
Track roller	80%		
Link assy	90%		
Pads	70%		
WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	10%		
Discharge conveyor	20%		
Milling drum housing	70%		
Milling drum	70%		
Upper toolholder	70%		
Scraper / side plates	20%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✗	Bandrahmen verbogen, 2x Bandversteifungen gebrochen, Rahmen Verstärkungen schlecht verschweißt	
Axles	✓		
Other	✓		