

WIRTGEN STRAßENFRÄSEN W 100 F

GENERAL		BILDER
ID	18513	
Year	2009	
Working hours	7287	
Weight [to]	18,8	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSC	
Engine rating [kW]	209	
Emission standard	Tier3	
EPA	✓	
EQUIPMENT		
Milling drum [mm]	1000	
Cutting depth [mm]	350	
Folding conveyor belt	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensor - cable	2	
High pressure water cleaner	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓	Turbolader Rücklaufleitung schwitzt	
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓	3 Schläuche an Ventilblock hinter Schaltschrank schwitzig	
Pump	✓		
Motors	✓		
Cylinders	✓	Walzenschildzylinder leicht schwitzig, Aufnahmebandzylinder schwitzt, Abwurfbandschwenkzylinder schwitzt, Abwurfbandklappzylinder Links leicht schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓	Batterien schwach	
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	70%		
Track roller	70%		
Link assy	80%		
Pads	80%		
WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	10%	Girlande 1 fest, Girlande 2 rechte Rolle fest	
Discharge conveyor	30%		
Milling drum housing	60%		
Milling drum	60%		
Upper toolholder	30%	Mehrere Oberhalter mit Unterhalter verschweißt	
Scraper / side plates	20%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓	Fahrschifflagerung von Klappschiff verschlissen	
Other	✓		