

WIRTGEN STRAßENFRÄSEN W 250

GENERAL		BILDER
ID	18550	
Year	2013	
Working hours	10231	
Weight [to]	49	
Spare part book	✓	
ENGINE SPECIFICATION		
Manufacturer	Cummins + Cummins	
Engine [type]	QSX15 + QSL	
Engine rating [kW]	447 + 261	
Emission standard	EU Stage IIIa / EPA, Tier III	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
Milling drum [mm]	2200	
Cutting depth [mm]	330	
FCS - flexible cutter system	✓	
Milling drum turning device	✓	
Folding conveyor belt	✓	
Vacuum unit	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensors (cylinder)	✓	
High pressure water cleaner	✓	
Air compressor	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓	Schlauch von Lenkzylinder VL an der Verpressung leicht schwitzig	
Pump	✓		
Motors	✓		
Cylinders	✓	Lenkzylinder VL leicht schwitzig, Seitenschildzylinder HL leicht schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
sglass pane	✓		
Display / buttons	✓	Bedienpult rechts Höhenverstellungsschalter links federrückstellung defekt und Höhenverstellungsschalter rechts abgebrochen	
Heating	✓		
General condition	✓		

ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓	Fehler Spiegelverstellung (neue Sicherung brennt direkt durch)	
Battery	✓	Batterien schwach	
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	30%	Vorne: 40%, Hinten: 20%	
Track roller	60%		
Link assy	70%		
Pads	20%	Vorne: 20%; Hinten: 10%	
WEAR	STATUS	REMARKS	PICTURES
Primary conveyer	60%	Mittig ca 50cm eingeschnitten (geklammert)	
Discharge conveyer	70%	4. Untere Bandrolle defekt	
Milling drum housing	80%		
Milling drum	70%	Schweißnaht an 7 Unterhalter eingerissen	
Upper toolholder	10%		
Scraper / side plates	30%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		