

WIRTGEN STRAßENFRÄSEN W 120 FI

GENERAL		BILDER
ID	18576	     
Year	2014	
Working hours	6141	
Weight [to]	21,05	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSL 9	
Engine rating [kW]	224	
Emission standard	Tier4	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
Milling drum [mm]	1200	
Cutting depth [mm]	320	
Folding conveyor belt	✓	
Vacuum unit	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensor - cable	2	
Hight sensors (cylinder)	✓	
High pressure water cleaner	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	80%		
Track roller	70%		
Link assy	80%		
Pads	50%	VL: 50%; VR: 40%; HL: 80%; HR: 30%	
WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	30%		
Discharge conveyor	40%		
Milling drum housing	70%		
Milling drum	60%		
Upper toolholder	50%		
Scraper / side plates	20%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✗	Fräswalzenschutz verbogen, Bandversteifung von Abwurfband schweißnähte gerissen oder schlecht verschweißt	
Axles	✓		
Other	✓		