WIRTGEN STRAßENFRäSEN W 100 F

GENERAL		BILDER
ID	18706	
Year	2011	
Working hours	7200	
Weight [to]	19	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSC	
Engine rating [kW]	209	
Emission standard	Tier3	
EPA	✓	
EQUIPMENT		
Milling drum [mm]	1000	
Cutting depth [mm]	300	
Folding conveyor belt	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensor - cable	2	
High pressure water cleaner	✓	

CONDITION			
ENGINE	**STATUS**	**REMARKS**	**PICTURES**
Engine oil	✓		
Leaks	✓	Motorölkühler schwitzt leicht	
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	**STATUS**	**REMARKS**	**PICTURES**
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Abwurfbandklappzylinder Rechts schwitzt, Abwurfbandschwenkzylinder leicht schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR´S STAND	**STATUS**	**REMARKS**	**PICTURES**
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	**STATUS**	**REMARKS**	**PICTURES**
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	80%		
Track roller	80%		
Link assy	80%		
Pads	80%		
WEAR	**STATUS**	**REMARKS**	**PICTURES**
Primary conveyor	50%		
Discharge conveyor	60%		
Milling drum housing	60%		
Milling drum	60%		
Upper toolholder	50%		
Scraper / side plates	60%		
OTHERS	**STATUS**	**REMARKS**	**PICTURES**
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓	Bandrahmen leicht verbogen, Bandrahmen an Klappzylinder links und rechts gerissen, Verstärkungen unsauber verschweißt	
Axles	✓		
Other	✓		