

## WIRTGEN STRAßENFRÄSEN W 100 F

GENERAL		BILDER
ID	18706	
Year	2011	
Working hours	7200	
Weight [to]	19	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSC	
Engine rating [kW]	209	
Emission standard	Tier3	
EPA	✓	
EQUIPMENT		
Milling drum [mm]	1000	
Cutting depth [mm]	300	
Folding conveyor belt	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensor - cable	2	
High pressure water cleaner	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓	Motorölkühler leicht schwitzig, Motorölablassschlauch schwitzt(durch gescheuert)	
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Abwurfbandklappzylinder Rechts schwitzt, Abwurfbandschwenkzylinder leicht schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	80%		
Track roller	80%		
Link assy	80%		
Pads	80%		
WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	30%		
Discharge conveyor	40%		
Milling drum housing	60%		
Milling drum	60%		
Upper toolholder	50%		
Scraper / side plates	60%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓	Bandrahmen leicht verbogen, Bandrahmen an Klappzylinder links und rechts gerissen, Verstärkungen unsauber verschweiß	
Axles	✓		
Other	✓		