

WIRTGEN BODENFRÄSEN/-RECYCLER WR 200I

GENERAL		BILDER
ID	18716	     
Year	2019	
Working hours	6238	
Weight [to]	23,8	
Manual	✓	
CE conformity	✓	
ENGINE SPECIFICATION		
Manufacturer	Mercedes	
Engine [type]	OM470LA	
Engine rating [kW]	320	
Emission standard	Tier4 final (mit Ad-Blue)	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
Cutting width [mm]	2000	
Cutting depth [mm]	500	
Air-conditioning	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓	Vier Schläuche von Ventilblock hinter der Kabine schwitzen an der Verpressung	
Pump	✓		
Motors	✓		
Cylinders	✓	Lenkzylinder HR schwitzt	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
sglass pane	✓		
Display / buttons	✓		
AC	✓		
Heating	✓		
General condition	✓		

ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Tires fl	30%		
Tires fr	90%		
Tires bl	90%		
Tires br	70%		
WEAR	STATUS	REMARKS	PICTURES
Milling drum housing	80%		
Milling drum	70%		
Upper toolholder	70%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		