

WIRTGEN STRAßENFRÄSEN W 1300 F

GENERAL		BILDER
ID	18734	     
Year	2001	
Working hours	9512	
Weight [to]	18,4	
ENGINE SPECIFICATION		
Manufacturer	Deutz	
Engine [type]	BF6M 1013 CP	
Engine rating [kW]	181	
EPA	✓	
EQUIPMENT		
Milling drum [mm]	1300	
Cutting depth [mm]	300	
Conveyor belt	✓	
Milling depth controller [pcs.]	2	
Hight sensor - cable	2	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓	Flansch zwischen Turbolader und Ölrücklauf schwitzt, Schlauch von Kurbelgehäuseentlüftung durchgescheuert, Kurbelgehäuseentlüftung schwitzt	
Blow by	✓		
Engine starting	✓		
Smoke	✓	Grau-Bläuliche Trübung des Abgasen	
Exhaust system	✓	Abgaskrümmer undicht	
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Lenkzylinder schwitzt	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓	Sitzpolster verschlissen	
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓	Frästifenregler rechts erkennt keinen Sensor	
Battery	▲	Batterien leer	
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Tires fl	70%		
Tires fr	60%		
Tires bl	80%		
Tires br	30%		
WEAR	STATUS	REMARKS	PICTURES
Primary conveyor	30%		
Discharge conveyor	10%		
Milling drum housing	70%		
Milling drum	50%	Oberhalter mit Unterhalter verschleißt	
Upper toolholder	30%		
Scraper / side plates	80%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓	An letzter Versteifung von Abwurfband schweißnähte gerissen	
Axles	✓		
Other	✓		