

## WIRTGEN STRAßENFRÄSEN W 250I

| GENERAL                     |                           | BILDER |
|-----------------------------|---------------------------|--------|
| ID                          | 18757                     |        |
| Year                        | 2017                      |        |
| Working hours               | 10479                     |        |
| Weight [to]                 | 45                        |        |
|                             |                           |        |
| ENGINE SPECIFICATION        |                           |        |
| Manufacturer                | Cummins + Cummins         |        |
| Engine [type]               | QSX15 600 + QSL9 380      |        |
| Engine rating [kW]          | 447 + 283                 |        |
| Emission standard           | Tier4 final (mit Ad-Blue) |        |
| EPA                         | ✓                         |        |
| exhaust gas after-treatment | ✓                         |        |
| EQUIPMENT                   |                           |        |
| Milling drum [mm]           | 2200                      |        |
| Cutting depth [mm]          | 330                       |        |
| Milling drum turning device | ✓                         |        |
| Folding conveyor belt       | ✓                         |        |
| Vacuum unit                 | ✓                         |        |
| VCS - Vacuum Cutting System | ✓                         |        |
| LEVEL PRO                   | ✓                         |        |
| Slope control sensor        | ✓                         |        |
| Hight sensors (cylinder)    | ✓                         |        |
| High pressure water cleaner | ✓                         |        |
| Air compressor              | ✓                         |        |

| CONDITION         |        |         |          |
|-------------------|--------|---------|----------|
| ENGINE            | STATUS | REMARKS | PICTURES |
| Engine oil        | ✓      |         |          |
| Leaks             | ✓      |         |          |
| Blow by           | ✓      |         |          |
| Engine starting   | ✓      |         |          |
| Smoke             | ✓      |         |          |
| Exhaust system    | ✓      |         |          |
| Cooling           | ✓      |         |          |
| General condition | ✓      |         |          |
| HYDRAULICS        | STATUS | REMARKS | PICTURES |
| Hoses             | ✓      |         |          |
| Pump              | ✓      |         |          |
| Motors            | ✓      |         |          |
| Cylinders         | ✓      |         |          |
| Leaks             | ✓      |         |          |
| General condition | ✓      |         |          |
| OPERATOR'S STAND  | STATUS | REMARKS | PICTURES |
| Seat              | ✓      |         |          |
| sglass pane       | ✓      |         |          |
| Display / buttons | ✓      |         |          |
| Heating           | ✓      |         |          |
| General condition | ✓      |         |          |
| ELECTRIC          | STATUS | REMARKS | PICTURES |
| lights            | ✓      |         |          |
| Starter           | ✓      |         |          |
| Electronic        | ✓      |         |          |
| Battery           | ✓      |         |          |
| General condition | ✓      |         |          |

| UNDERCARRIAGE         | STATUS | REMARKS                      | PICTURES |
|-----------------------|--------|------------------------------|----------|
| Sprockets             | 50%    | VL&VR: 90%, HL: 20%, HR: 10% |          |
| Track roller          | 70%    |                              |          |
| Link assy             | 60%    |                              |          |
| Pads                  | 80%    |                              |          |
| WEAR                  | STATUS | REMARKS                      | PICTURES |
| Primary conveyor      | 20%    |                              |          |
| Discharge conveyor    | 40%    |                              |          |
| Milling drum housing  | 80%    |                              |          |
| Milling drum          | 80%    |                              |          |
| Upper toolholder      | 90%    |                              |          |
| Scraper / side plates | 20%    |                              |          |
| OTHERS                | STATUS | REMARKS                      | PICTURES |
| Gearbox               | ✓      |                              |          |
| Brake                 | ✓      |                              |          |
| Drive                 | ✓      |                              |          |
| Frame                 | ✓      |                              |          |
| Axles                 | ✓      |                              |          |
| Other                 | ✓      |                              |          |