

WIRTGEN STRAßENFRÄSEN W 130 CFI

GENERAL		BILDER
ID	18760	     
Year	2017	
Working hours	6537h	
Weight [to]	20,5	
Spare part book	✓	
ENGINE SPECIFICATION		
Manufacturer	Cummins	
Engine [type]	QSL 9 333	
Engine rating [kW]	248	
Emission standard	Tier4 final (mit Ad-Blue)	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
Milling drum [mm]	1300	
Cutting depth [mm]	330	
FCS - flexible cutter system	✓	
Milling drum turning device	✓	
Folding conveyor belt	✓	
VCS - Vacuum Cutting System	✓	
LEVEL PRO	✓	
Slope control sensor	✓	
Hight sensors (cylinder)	✓	
High pressure water cleaner	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Lenkzylinder Vorne schwitzt leicht	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓	Schalter defekt siehe foto (Schalter nicht belegt)	
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓	Kabelbruch Ultraschallsensor abstreifer	
Battery	✓		
General condition	✓		

UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	80%		
Track roller	70%		
Link assy	80%		
Pads	90%		
WEAR	STATUS	REMARKS	PICTURES
Other	80%		
Primary conveyor	70%		
Discharge conveyor	80%		
Milling drum housing	80%		
Milling drum	70%		
Upper toolholder	60%		
Scraper / side plates	70%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓	Schweißnaht an Klappschiff eingerissen	
Axles	✓		
Other	✓	Luftfilterkastendeckel gebrochen	