

## CATERPILLAR KETTENBAGGER 314 D LCR

GENERAL		BILDER
ID	18396	
Year	2012	
Working hours	9903	
Weight [to]	16,9	
Manual	✓	
Spare part book	✓	
ENGINE SPECIFICATION		
Manufacturer	Caterpillar	
Engine [type]	C4.2	
Engine rating [kW]	67	
Emission standard	Tier 3b/4i	
last service [h]	12/2023 bei 9900h	
exhaust gas after-treatment	✓	
EQUIPMENT		
digging depth [cm]	491	
ditch-cleaning-bucket hydr. [cm]	180	
track pad [mm]	500	
Hammer lines	✓	
crusher lines	✓	
blade stabilizer	✓	
Quick coupler hydr.	✓	
Quick coupler [type]	Verachttert CW 20	
central lubrication	✓	
Air-conditioning	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓		
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
sglass pane	✓		
Display / buttons	✓		
AC	✓		
Heating	✓		
General condition	✓		

ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	40%		
Idler	80%		
Track roller	70%		
Link assy	50%		
Pads	70%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓	Tankdeckel defekt (Verriegelt nicht mehr) ; Mittig im Planierschild sind Risse (Verschleiß)	