

HITACHI KETTENBAGGER ZX 135 US-6

GENERAL		BILDER
ID	18448	     
Year	2018	
Working hours	8978	
Weight [to]	14,7	
ENGINE SPECIFICATION		
Manufacturer	Isuzu	
Engine [type]	4JJ1	
Engine rating [kW]	78,5	
Emission standard	Tier4f	
last service [h]	8640h / 23.08.24	
EPA	✓	
exhaust gas after-treatment	✓	
EQUIPMENT		
digging depth [cm]	550	
bucket [cm]	80	
Bucket [piece]	1	
track pad [mm]	500	
grab slewing device	✓	
Hammer lines	✓	
crusher lines	✓	
blade stabilizer	✓	
Quick coupler hydr.	✓	
Quick coupler [type]	OilQuick OQ65	
central lubrication	✓	
Air-conditioning	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		
HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Hubzylinder Links leicht schwitzig	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
sglass pane	✓		
Display / buttons	✓		
AC	✓		
Heating	✓		
General condition	✓		

ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓	Seitenkamera ohne Funktion (Kabel abgequetscht)	
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Sprockets	60%		
Idler	80%		
Track roller	80%		
Link assy	60%		
Pads	80%		
OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		