

AUSA DUMPER BIS 10 T D 1000 APG

GENERAL		BILDER
ID	18730	     
Year	2017	
Working hours	2856	
Weight [to]	3,5	
ENGINE SPECIFICATION		
Manufacturer	Deutz	
Engine [type]	TCD 3.6 L4	
Engine rating [kW]	70	
exhaust gas after-treatment	✓	
EQUIPMENT		
payload [to]	10	
body [m³]	4,8 gehäuft	
All wheel drive	✓	

CONDITION			
ENGINE	STATUS	REMARKS	PICTURES
Engine oil	✓		
Leaks	✓		
Blow by	✓		
Engine starting	✓		
Smoke	✓		
Exhaust system	✓		
Cooling	✓		
General condition	✓		

HYDRAULICS	STATUS	REMARKS	PICTURES
Hoses	✓		
Pump	✓		
Motors	✓		
Cylinders	✓	Kolbenstange von Lenkzylinder verkratzt	
Leaks	✓		
General condition	✓		
OPERATOR'S STAND	STATUS	REMARKS	PICTURES
Seat	✓		
Display / buttons	✓		
General condition	✓		
ELECTRIC	STATUS	REMARKS	PICTURES
lights	✓		
Starter	✓		
Electronic	✓		
Battery	✓		
General condition	✓		
UNDERCARRIAGE	STATUS	REMARKS	PICTURES
Tires fl	90%		
Tires fr	90%		
Tires bl	60%	Felgenhorn eingedrückt	
Tires br	60%		
WEAR	STATUS	REMARKS	PICTURES
Other	70%		

OTHERS	STATUS	REMARKS	PICTURES
Gearbox	✓		
Brake	✓		
Drive	✓		
Frame	✓		
Axles	✓		
Other	✓		