

HAMM KOMBIWALZE HD 10I VT

GENERAL		BILDER
ID	18736	
anul de fabricatie	2016	
ore	4690	
greutate [to]	2,5	
manual de utilizare	✓	
Lista de piese de schimb	✓	
CE Declara?ia de conformitate	✓	
DATELE MOTORULUI		
producator	Kubota	
motor [tip]	D1503-M-EU33	
capacitatea motorului [kW]	24	
emisii standard	Tier3 A	
Ultimul serviciu [h]	4688h/29.01.26	
ECHIPAMENT		
Kantenschneidergerät [Stück]	1	

STARE			
MOTOR	STATUS	ANMERKUNGEN	POZE
ulei motor	✓		
Leckagen	✓		
Leckgas	✓		
Anspringverhalten	✓		
fum	✓		
Auspuffanlage	✓		
Kühler	✓		
starea general?	✓		

HIDRAULICA	STATUS	ANMERKUNGEN	POZE
furtuni	✓		
Pumpe	✓		
motor	✓		
Zylinder	✓		
Leckagen	✓		
starea general?	✓		
CABINA	STATUS	ANMERKUNGEN	POZE
Sitz	✓		
Display/Schalter	✓		
starea general?	✓		
ELEKTRIK	STATUS	ANMERKUNGEN	POZE
iluminat	✓		
starter	✓		
electronic?	✓		
baterii	✓		
starea general?	✓		
FAHRWERK	STATUS	ANMERKUNGEN	POZE
Reifen hl	60%		
Reifen hr	40%		
VERSCHLEISS	STATUS	ANMERKUNGEN	POZE
Abstreifer	50%		
Bandagengummis	30%	Bandagengummis Links eingerissen	
Bandage	60%	12mm	

SONSTIGES	STATUS	ANMERKUNGEN	POZE
Getriebe	✓		
Bremsen	✓		
Fahrantrieb	✓		
Rahmen	✓		
Achsen	✓		
alte	✓		