

WIRTGEN BODENFRÄSEN/-RECYCLER WR 200I

GENERAL		BILDER
ID	18716	     
anul de fabricatie	2019	
ore	6238	
greutate [to]	23,8	
manual de utilizare	✓	
CE Declara?ia de conformitate	✓	
DATELE MOTORULUI		
producator	Mercedes	
motor [tip]	OM470LA	
capacitatea motorului [kW]	320	
emisii standard	Tier4 final (mit Ad-Blue)	
EPA plac?	✓	
Filtru diesel disponibil	✓	
ECHIPAMENT		
latimea frezei [mm]	2000	
adincimea frezei [mm]	500	
instalatie pentru aer conditionat	✓	

STARE			
MOTOR	STATUS	ANMERKUNGEN	POZE
ulei motor	✓		
Leckagen	✓		
Leckgas	✓		
Ansprungsverhalten	✓		
fum	✓		
Auspuffanlage	✓		
Kühler	✓		
starea general?	✓		
HIDRAULICA	STATUS	ANMERKUNGEN	POZE
furtuni	✓	Vier Schläuche von Ventilblock hinter der Kabine schwitzen an der Verpressung	
Pumpe	✓		
motor	✓		
Zylinder	✓	Lenkzylinder HR schwitzt	
Leckagen	✓		
starea general?	✓		
CABINA	STATUS	ANMERKUNGEN	POZE
Sitz	✓		
Scheiben	✓		
Display/Schalter	✓		
aer condi?ionat	✓		
înc?lzire	✓		
starea general?	✓		

ELEKTRIK	STATUS	ANMERKUNGEN	POZE
iluminat	✓		
starter	✓		
electronic?	✓		
baterii	✓		
starea general?	✓		
FAHRWERK	STATUS	ANMERKUNGEN	POZE
Reifen vl	30%		
Reifen vr	90%		
Reifen hl	90%		
Reifen hr	70%		
VERSCHLEISS	STATUS	ANMERKUNGEN	POZE
Fräskasten	80%		
tambur	70%		
Oberhalter	70%		
SONSTIGES	STATUS	ANMERKUNGEN	POZE
Getriebe	✓		
Bremsen	✓		
Fahrantrieb	✓		
Rahmen	✓		
Achsen	✓		
alte	✓		