

WIRTGEN STRAßENFRÄSEN W 250I

GENERAL		BILDER
ID	18763	     
anul de fabricatie	2017	
ore	8054	
greutate [to]	45	
DATELE MOTORULUI		
producator	Cummins + Cummins	
motor [tip]	QSX15 600 + QSL9 380	
capacitatea motorului [kW]	447 + 283	
emisii standard	Tier4 final (mit Ad-Blue)	
EPA plac?	✓	
Filtru diesel disponibil	✓	
ECHIPAMENT		
Tambur de frezat	2200	
adincimea frezei [mm]	330	
band?	✓	
Sistemul de extrac?ie VCS	✓	
LEVEL PRO	✓	
Senzor de panta	✓	
Senzori de m?surare a distan?ei (cilindri)	✓	
Masina de spalat cu presiune	✓	
compresor	✓	

STARE			
MOTOR	STATUS	ANMERKUNGEN	POZE
ulei motor	✓		
Leckagen	✓		
Leckgas	✓		
Ansprungsverhalten	✓		
fum	✓		
Auspuffanlage	✓		
Kühler	✓		
starea general?	✓		
HIDRAULICA	STATUS	ANMERKUNGEN	POZE
furtuni	✓		
Pumpe	✓		
motor	✓		
Zylinder	✓	Seitenschildzylinder VL schwitzt und Bolzen fehlt	
Leckagen	✓		
starea general?	✓		
CABINA	STATUS	ANMERKUNGEN	POZE
Sitz	✓		
Scheiben	✓	Frontscheibe gerissen und Stücke heraus gebrochen	
Display/Schalter	✓		
starea general?	✓		
ELEKTRIK	STATUS	ANMERKUNGEN	POZE
iluminat	✓		
starter	✓		
electronic?	✓		
baterii	✓		
starea general?	✓		

FAHRWERK	STATUS	ANMERKUNGEN	POZE
Turas	70%		
Lauf/ Tragrollen	60%		
Kettenbänder	60%		
Bodenplatten / Pads	70%	VL: 90%; VR: 90%; HL: 10%; HR: 50%	
VERSCHLEISS	STATUS	ANMERKUNGEN	POZE
Aufnahmeband	50%		
Abwurfband	60%		
Fräskasten	80%		
tambur	70%		
Oberhalter	70%		
Abstreifer / Schild	60%		
SONSTIGES	STATUS	ANMERKUNGEN	POZE
Getriebe	✓		
Bremsen	✓		
Fahrantrieb	✓		
Rahmen	✓		
Achsen	✓		
alte	✓		