

LIEBHERR LADERAUPE LR 636

????? ????????????????		BILDER
ID	18147	     
??? ???????	2015	
?????????	10526	
??? [?]	24	
?????		
????????????????	Liebherr	
????? [???	D934 A7-14	
????????? ?????????? [???	135	
?????????? ????????	Tier 4 Final	
?????????? ??????????	10129h / 31.10.22	
EPA ??????	✓	
?????????? ??????? ? ????????	✓	
????????????????		
?????? ?????????[??]	560	
?????????????? ????	2,5	
??????????????	✓	

??????????			
?????	?????	??????????	??????????
??????????	✓		
??????	✓		
Leckgas	✓		
Ansprungsverhalten	✓		
???	✓		
??????????	✓		
??????????	✓		
????? ?????????	✓		
??????????	?????	??????????	??????????
??????	✓		
?????	✓		
??????	✓		
???????	✓		
??????	✓		
??????	✓		
????? ?????????	✓		
??????	?????	??????????	??????????
????????	✓		
??????	✓		
????????	✓		
AC	✓		
??????????	✓		
????? ?????????	✓		
????? ?????????	✓		

????????????????	??????	??????????	??????????
??????????	✓		
????????	✓		
????????????	✓		
????????????	✓		
????? ??????????	✓		
?????	??????	??????????	??????????
Turas	30%		
??????	70%		
Kettenbänder	70%		
??????	60%		
?????	??????	??????????	??????????
??????	80%		
??????	??????	??????????	??????????
??????????	✓		
????????	✓		
???????? ??????	✓		
????	✓	Schloss von Seitenklappe VL defekt	
???	✓		
??????	✓		